Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC.
Well Operator: XTO ENERGY INC.
Well Name: SORENSON 34-32NWH

Field Name: SIVERSTON Well File #: 20012

Date Incident:8/9/2014Time Incident:11:00Facility ID Number:County:MCKENZIETwp: 150Rng: 98Sec: 32Qtr:

Location Description:

Submitted By: Kaylan Dirkx Received By:

Contact Person: Kaylan Dirkx

P.O Box 1589

Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spillea	Units	Recoverea	Units	
Oil	2	Barrels	1	Barrels	
Brine	1	Barrels	1	Barrels	
Bille		Daliels		Daileis	

Other

Description of Other Released Contaminant:

Cuillad Iluita

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None- spill was contained on location.

Areal Extent:

Followup Units

Potential Environmental Impacts:

None-spill was contained on location.

Action Taken or Planned:

Vac truck recovered 2 bbls of liquid and returned to production tanks. Impacted soil will be removed and disposed at an approved facility.

Wastes Disposal Location: Indian Hills disposal

Agencies Involved:

Updates

Date: 8/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.